


Color Chart WB EPOXY

THOUGHTFULLY DESIGNED COATINGS

Available in **Clear** and in the following colors:



BEST PRACTICES

- Appearance: Colors are approximate. Final look may vary based on product, substrate, mix ratio, technique, climate, and location.
- Batching: Use the same batch number for consistent color. If batches differ, mix them together until the color is uniform.
- Testing: Always test material in the application area before starting full installation.
- Mixing: Thoroughly mix Part A until color is uniform before combining with other components. If adding colorant, mix color with Clear Part A until uniform before combining.
- Light colors (marked with *): May require two coats at thin mil thickness to achieve full hide.
- Prime and base coats: Choose colors that match or support the final look, as they may affect the appearance or coverage requirements of the top coat.
- UV resistance: All epoxy will amber over time. For better color stability, use a UV-resistant coating such as Polyaspartic or Polyurethane.
- For custom color: Complete the Special Order Form (kretus.com/special-order-form). Additional fees and lead times apply.